

Note: 000066

Overview

Number	000066
Description	License Installation Issue After System Copy With SID Rename
Version	2 from 11.07.2017
Status	Released to Customer
Language	EN
Responsible	Günter Spens
Product	BCS
Category	Correction - PMC & GMC

Symptom

In some cases, after performing an SAP system copy with SID rename, a product license can be reported as installed, but after the installation, the license does not show as being active. Licenses from the source system for additional products may be shown as active.

Cause

N/A

Solution

1. EITHER Apply the attached transport to the source system before the system copy.
OR, if this is not possible, apply the attached transport to the target system(s) after the system copy.
NOTE: as this is a code fix, it is client independent.

2. Apply the specific product key to the target system as usual. This code change cleans invalid keys from the system during license key application.
3. After the application of the key(s) you should see the expected message for your system and product(s). Only when this message is displayed have you confirmed the installation of the appropriate license:

In the example below, system "COI", product BCP, a limited duration license:

```
Bulk Calculations - Petroleum
System Client Validity
COI  ALL  Temporary license, valid, last day: 05.02.2017
```

Transport Reference

SAP Release	Transport	File Name	Notes
ECC600	QOIK900264	NOTE-00066-600.SAR	

Validity

SAP Release	From SP	To SP	In SP Shipment
ECC600	10B CSP03	-	BCS 3.0